

TEST REPORT

Mechanical & Hardgoods Laboratory

Report No.: HLO0307/2016

Page : 1 of 2 Date : OCT. 26, 2016

Hun Tai Plastic Co., Ltd.

47-7 Annan Ln, Hsiushui, Changhwa, 504 Taiwan

The following merchandise was submitted and identified by the applicant as:

<u>Product Description:</u> Chair Base Style/Item No.: HTI-300

Manufacturer/Vendor: Hun Tai Plastic Co., Ltd.

Country of Origin: Taiwan

We have tested the submitted sample(s) as requested and the following results were obtained:

<u>Test Requested:</u> For compliance with ANSI/BIFMA X5.1-2011 General-Purpose Office

Chairs-Tests

Sect. 07 Base Test – Static

<u>Test Methods:</u> According to test procedures of ANSI/BIFMA X5.1-2011

<u>Test Results:</u> ---See following sheet(s)---

Date of Receipt: Oct. 18, 2016

<u>Testing Period:</u> Oct. 18, 2016 ~ Oct. 26, 2016

Conclusion: The submitted sample **comply with** Sect. 07 of ANSI/BIFMA X5.1-2011

General-Purpose Office Chairs-Tests.

Signed for and on be SGS Taiwan Ltd.

Lawrence Yang Asst. Supervisor

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced, except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested

SGS Taiwan Ltd.

No.127, Wu Kung Road, New Taipei Industrial Park, New Taipei City, Taiwan /新北市新北產業園區五工路 127 號

www.tw.sgs.com



TEST REPORT

Mechanical & Hardgoods Laboratory

Report No.: HLO0307/2016


Page : 2 of 2

Evaluation	Citation/Method	Criteria		Rating
PERFORMANCE				
Base Test Static	ANSI/BIFMA X5.1-2011 Clause 7	No sudden and major change in the structural integrity after 11,120 N (2500 lb.) compression for 1 min. The weight is then removed and reapplied for 1 min. The center column may not touch the test platform during load applications.	M	Pass

Results Key:						
M	Meets	N/M	Does Not Meet			
N/A	Not Applicable	N/T	Not Tested			
C	Claimed	R	Recorded			

Rating Key:	
Pass	
Fail	

– Pictures –



---End of Report---



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sqs.com/en/Terms-and-Conditions/sepsy. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced, except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested

No.127, Wu Kung Road, New Taipei Industrial Park, New Taipei City, Taiwan /新北市新北產業園區五工路 127 號 t (886-2) 2299-3279 www.tw.sgs.com

台灣檢驗科技股份有限公司

f (886-2) 2299-2920

Member of SGS Group